



CN

Lead in Drinking Water Analysis Report

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Report Number: 21-08-03512
Received Date: 08/23/2021
Reported Date: 08/30/2021
Sampled By: Krishi Tanna
Tech Certification #:

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Project/Test Address: 210133; Constable; 29 Constable Rd; Kendall Park, NJ 08824

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-08-03512-001	CON-S-01	08/11/2021	KITCHEN LEFT	9.39	08/25/2021	
21-08-03512-002	CON-S-02	08/11/2021	KITCHEN RIGHT	3.98	08/25/2021	
21-08-03512-003	CON-S-03	08/11/2021	KITCHEN BY ITSELF	2.81	08/25/2021	
21-08-03512-004	CON-S-04	08/11/2021	KITCHEN FRNT LFT NXT	3.21	08/25/2021	
21-08-03512-005	CON-S-05	08/11/2021	KITCHEN FRNT RIGHT NEXT	3.87	08/25/2021	
21-08-03512-006	CON-S-06	08/11/2021	KITCHEN RIGHT BY POT FILLER	2.30	08/25/2021	
21-08-03512-007	CON-B-09	08/11/2021	RM D402	<1.00	08/25/2021	
21-08-03512-008	CON-B-10	08/11/2021	RM C305	6.51	08/25/2021	
21-08-03512-009	CON-B-11	08/11/2021	RM C304	1.44	08/25/2021	
21-08-03512-010	CON-B-12	08/11/2021	RM C303	2.00	08/25/2021	
21-08-03512-011	CON-B-13	08/11/2021	RM C302	<1.00	08/25/2021	
21-08-03512-012	CON-B-14	08/11/2021	RM C301	<1.00	08/25/2021	
21-08-03512-013	CON-WC-15	08/11/2021	HALL BY GYM LEFT	<1.00	08/25/2021	

Environmental Hazards Services, L.L.C

Client Number: 201327
 Project/Test Address: 210133; Constable; 29 Constable Rd; Kendall Park, NJ
 08824

Report Number: 21-08-03512

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-08-03512-014	CON-WC-16	08/11/2021	HALL BY GYM CENTER	<1.00	08/25/2021	
21-08-03512-015	CON-WC-17	08/11/2021	HALL BY GYM RIGHT	<1.00	08/25/2021	
21-08-03512-016	CON-B-18	08/11/2021	RM B207	2.60	08/25/2021	
21-08-03512-017	CON-B-19	08/11/2021	RM B206	55.0	08/25/2021	
21-08-03512-018	CON-B-20	08/11/2021	RM B205	3.38	08/25/2021	
21-08-03512-019	CON-B-21	08/11/2021	RM B204	99.7	08/25/2021	
21-08-03512-020	CON-B-22	08/11/2021	RM B203	7.89	08/25/2021	
21-08-03512-021	CON-B-23	08/11/2021	RM B202	27.8	08/25/2021	
21-08-03512-022	CON-S-25	08/11/2021	RM A107	9.59	08/25/2021	
21-08-03512-023	CON-B-26	08/11/2021	RM A106	4.23	08/25/2021	
21-08-03512-024	CON-B-27	08/11/2021	RM A105	9.79	08/25/2021	
21-08-03512-025	CON-B-28	08/11/2021	RM A104	13.3	08/25/2021	
21-08-03512-026	CON-B-29	08/11/2021	RM A103	5.23	08/25/2021	
21-08-03512-027	CON-B-30	08/11/2021	RM A102	13.4	08/25/2021	
21-08-03512-028	CON-S-31	08/11/2021	NURSE A101	3.94	08/25/2021	
21-08-03512-029	CON-B-32	08/11/2021	HALL TO STORAGE RM	6.50	08/25/2021	
21-08-03512-030	CON-WC-33	08/11/2021	F HALL LEFT	<1.00	08/25/2021	
21-08-03512-031	CON-WC-34	08/11/2021	F HALL RIGHT	<1.00	08/25/2021	
21-08-03512-032	CON-B-35	08/11/2021	RM F607	43.6	08/27/2021	W01
21-08-03512-033	CON-B-36	08/11/2021	RM F608	2.06	08/25/2021	

Environmental Hazards Services, L.L.C

Client Number: 201327
 Project/Test Address: 210133; Constable; 29 Constable Rd; Kendall Park, NJ
 08824

Report Number: 21-08-03512

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-08-03512-034	CON-B-37	08/11/2021	RM F609	1.49	08/25/2021	
21-08-03512-035	CON-B-38	08/11/2021	RM F610	<1.00	08/25/2021	
21-08-03512-036	CON-B-39	08/11/2021	HALL BY RM G705	1.34	08/25/2021	
21-08-03512-037	CON-B-40	08/11/2021	HALL BY RM G705 LEFT	1.04	08/25/2021	
21-08-03512-038	CON-B-41	08/11/2021	HALL BY RM G705 RIGHT	2.36	08/25/2021	
21-08-03512-039	CON-B-42	08/11/2021	RM G705	1.43	08/25/2021	
21-08-03512-040	CON-B-43	08/11/2021	RM G706	1.84	08/25/2021	
21-08-03512-041	CON-B-44	08/11/2021	RM G707	3.58	08/25/2021	
21-08-03512-042	CON-B-45	08/11/2021	RM G708	8.90	08/25/2021	
21-08-03512-043	CON-B-46	08/11/2021	HALL BY E501 LEFT	5.58	08/25/2021	
21-08-03512-044	CON-B-48	08/11/2021	RM E501	<1.00	08/25/2021	
21-08-03512-045	CON-S-49	08/11/2021	NXT TO EXIT	<1.00	08/25/2021	

Sample Narratives:

W01: MB exceeded acceptance limit for Pb.

Environmental Hazards Services, L.L.C

Client Number: 201327
Project/Test Address: 210133; Constable; 29 Constable Rd; Kendall Park, NJ
08824

Report Number: 21-08-03512

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
-------------------	------------------	-----------------	---------------------	--------------------------	---------------	--------------

Method: EPA 200.8
Analyst: Ailea Cabatbat
Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Missy Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



EHSO Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com
Phone: (800) 347-4010 FAX: (004) 275-4907

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237

Company Name: LEW CORP Account #: 201327

Address: 181 US Highway 46 City/State/Zip: Mine Hill, NJ 07803

Phone: 1908-654-9058 Email: labresults@lewecorp.com Fax: 908-654-8069

Project Name / Collection Address: CONSTABLE; 29 CONSTABLE RD City/State/Zip: KENDALL PARK, NJ, 08

Project #: 210133 Sampled by: Krishi Tanna License # (If Required):

Water Source: (Check One) Public Well Well Tag # (If Applicable):

No.	Client Sample ID	Collection Location (Eg: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters			LAB USE
					Lead	Copper	Other	Field pH at Time of Collection	Temp. at Time of Collection	Temp at Time of Receipt	
1	CON-S-01	KITCHN - LEFT	8/11/2021	9:45 - 11:15 AM	X						
2	CON-S-02	KITCHN - RIGHT	8/11/2021	9:45 - 11:15 AM	X						
3	CON-S-03	KITCHN - BY ITSELF	8/11/2021	9:45 - 11:15 AM	X						
4	CON-S-04	KITCHN - FRNT LFT NXT	8/11/2021	9:45 - 11:15 AM	X						
5	CON-S-05	KITCHN - FRNT RIGHT NXT	8/11/2021	9:45 - 11:15 AM	X						
6	CON-S-06	KITCHN - RIGHT BY POT FILLER	8/11/2021	9:45 - 11:15 AM	X						
7	CON-B-09	RM D402	8/11/2021	9:45 - 11:15 AM	X						
8	CON-B-10	RM C305	8/11/2021	9:45 - 11:15 AM	X						
9	CON-B-11	RM C304	8/11/2021	9:45 - 11:15 AM	X						
10	CON-B-12	RM C303	8/11/2021	9:45 - 11:15 AM	X						

Released by: Krishi Tanna
KT14082021

Signature: *[Signature]*

Date/Time: 8/11/2021

Date/Time: 8/23/21

Signature: *[Signature]*
HTAM



21-08-03512

Due Date:
08/30/2021
(Monday)
AE



EHSO
Laboratories
ENVIRONMENTAL HAZARDOUS SERVICES, LLC

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 Fax: (804) 275-4907

~ For Lab Use Only ~

Company Name: LEW CORP Account #: 201327

Address: 181 US Highway 46 City/State/Zip: Mine Hill, NJ 07803

Phone: 1908-654-8063 Email: labresults@lewcorn.com Fax: 908-654-8069

3512

Project Name / Collection Address: CONSTABLE; 29 CONSTABLE RD City/State/Zip: KENDALL PARK, NJ 08824
(Required)

Project #: 210133 Sampled By: Krishni Tanna License #: (If Required):

Water Source: (Check One) Public Well Well Tag #: (If Applicable):

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		
					Lead	Copper	Other	Field pH at time of collection:	Temp. at time of collection:	Temp. at Time of Receipt:
21	CON- B- 23	RM B202	8/11/2021	9:45 - 11:15 AM	X					
22	CON- S- 25	RM A107	8/11/2021	9:45 - 11:15 AM	X					
23	CON- B- 26	RM A106	8/11/2021	9:45 - 11:15 AM	X					
24	CON- B- 27	RM A105	8/11/2021	9:45 - 11:15 AM	X					
25	CON- B- 28	RM A104	8/11/2021	9:45 - 11:15 AM	X					
26	CON- B- 29	RM A103	8/11/2021	9:45 - 11:15 AM	X					
27	CON- B- 30	RM A102	8/11/2021	9:45 - 11:15 AM	X					
28	CON- S- 31	NURSE A101	8/11/2021	9:45 - 11:15 AM	X					
29	CON- B- 32	HALL TO STORAGE RM	8/11/2021	9:45 - 11:15 AM	X					
30	CON- WC- 33	F HALL- LEFT	8/11/2021	9:45 - 11:15 AM	X					

Released by: Krishni Tanna Signature: [Signature] Date/Time: 8/11/2021

Released by: KTHAWAS Signature: [Signature] Date/Time: 8/23/21 11:17 AM



ENVIRONMENTAL HAZARDS SERVICES, LLC

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

Water Chain-of-Custody Form

SHIP TO: 7459 Wilkepine Rd, Richmond, VA 23237
Phone (800) 347-4010 FAX: (804) 275-4907

~ For Lab Use Only ~

Company Name: LEW CORP
Address: 181 US Highway 46
City/State/Zip: _____
Phone: 908-554-8069
Email: labresults@lewcop.com
Fax: 908-654-8069

2572

Project Name / Collection Address: CONSTABLE, 29 CONSTABLE RD
Project #: 210133
Sampled by: Krishni Tanna
City/State/Zip: KENDALL PARK, NJ, 08824
License #: (if Required): _____

Water Source: (Check One) Public Well _____
(Required) Well Tag #: (if Applicable) _____

No.	Client Sample ID	Collection Location (Eg: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters			
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	LAB USE Temp at Time of Receipt:	
81	CON- WC - 34	F HALL RIGHT	8/11/2021	9:45 - 11:15 AM	X						
32	CON- B - 35	RM F607	8/11/2021	9:45 - 11:15 AM	X						
33	CON- B - 36	RM F608	8/11/2021	9:45 - 11:15 AM	X						
34	CON- B - 37	RM F609	8/11/2021	9:45 - 11:15 AM	X						
35	CON- B - 38	RM F610	8/11/2021	9:45 - 11:15 AM	X						
36	CON- B - 39	HALL BY RM G705	8/11/2021	9:45 - 11:15 AM	X						
37	CON- B - 40	HALL BY RM G705 LEFT	8/11/2021	9:45 - 11:15 AM	X						
38	CON- B - 41	HALL BY RM G705 RIGHT	8/11/2021	9:45 - 11:15 AM	X						
39	CON- B - 42	RM G705	8/11/2021	9:45 - 11:15 AM	X						
40	CON- B - 43	RM G706	8/11/2021	9:45 - 11:15 AM	X						

Released by: Krishni Tanna Signature: [Signature]

Date/Time: 8/11/2021
Date/Time: 8.23.21
Date/Time: 11:08 AM



Environmental Hazards Services, LLC
 ENVIRONMENTAL HAZARDS SERVICES, LLC

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com
 Phone: (800) 347-4010 FAX: (804) 275-4907

Water Chain-of-Custody Form

~ For Lab Use Only ~

3512

Company Name: LEW CORP Account #: 201327
 Address: 181 US Highway 415 City/State/Zip: Millie Hill, NJ 07803
 Phone: 908-554-8068 Email: labresults@ewcorp.com Fax: 908-654-8069
 Project Name / Collection Address: CONSTABLE, 29 CONSTABLE RD City/State/Zip: KENDALL PARK, NJ, 08824
 (Required)
 Project #: 210133 Sampled By: Krishni Tanna License # (if Required):
 Water Source: (Check One) Public Well _____ Well Tag # (if Applicable): _____
 (Required)

No.	Client Sample ID	Collection Location (Et: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		
					Lead	Copper	Other	Field pH at time of Collection	Temp. at time of Collection	Temp at Time of Receipt
41	CON- B-44	RM G707	8/11/2021	9:45 - 11:15 AM	X					
42	CON- B-45	RM G708	8/11/2021	9:45 - 11:15 AM	X					
43	CON- B-46	HALL BY E501 LEFT	8/11/2021	9:45 - 11:15 AM	X					
44	CON- B-48	RM E501	8/11/2021	9:45 - 11:15 AM	X					
45	CON- S-49	NXT TO EXIT	8/11/2021	9:45 - 11:15 AM	X					
6	CON-				X					
7	CON-				X					
8	CON-				X					
9	CON-				X					
10	CON-				X					

Released by: Krishni Tanna Signature: [Signature] Date/Time: 8/11/2021
 Released by: KIHARUIS Signature: [Signature] Date/Time: 8/23/21
 Date/Time: 11:17 AM



ENVIRONMENTAL HAZARDS SERVICES, LLC

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907

Company Name: LEWCOBIP Account #: 201327

Address: 181 US HIGHWAY 46 City/State/zip: Mine Hill, NJ 07803

Phone: (908) 554-8068 Email: labresults@lewcorp.com Fax: 908-554-8069

Project Name / Collection Address: INDIAN FIELDS @ DAYTON, 310 GEORGES RD DAYTON, NJ, 08810

Project #: 210133 Sampled By: Krishi Tanna License # (if Required):

Water Source: (Check One) Public Well Well Tag # (if Applicable):

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection	Temp. at time of Collection	
1	IFD - B - 01	HALL ACROSS FROM GYM - R	8/6/2021	7:48 AM	X					
2	IFD - S - 02	KITCHEN LEFT	8/6/2021	7:52 AM	X					
3	IFD - S - 03	KITCHEN RIGHT	8/6/2021	8:00 AM	X					
4	IFD - B - 04	HALL - LEFT	8/6/2021	8:06 AM	X					
5	IFD - B - 05	HALL - RIGHT	8/6/2021	8:10 AM	X					
6	IFD - S - 06	NURSES	8/6/2021	8:16 AM	X					
7	IFD - S - 07	NEXT TO EXIT	8/6/2021	8:18 AM	X					
8										
9										
10										

Released by: KRISHI TANNA Signature: *[Signature]* Date/Time: 8/6/2021

Released by: KTHARRAIS Signature: *[Signature]* Date/Time: 8/23/21 1:03 PM

21-08-03607

Due Date: 08/30/2021 (Monday) AE